Peachtree Lane Reported Roof Leaks

	<u>မ</u>	28	27	26	25	23	21	13	12	10 & 11	· •	4	3	2	
:	×	×	×		×	×	×	×				×	×	×	
	×		1005 1 1 1	×	i S				· ·	×	: ×		. 12	=	
	Master bedroom leaks	Cracked Foam	Around a/c elbow	Broken tiles & tiles needed for 31. Tiles will be used after 31 is completed	Foam Repair	Foam bubbles	Foam Bubbles	Around a/c elbow	At a/c return inside home	Leak	Living room ceiling light fixture above couch	Full replacement of foam	Full replacement of foam	Around a/c elbow	
		×	×		×			×				×	×	×	
	×			×		×	×	. <u>. </u>	•	×	×				Roofing
The state of the s	Completed	Completed	Completed	Completed	Completed	OPEN	OPEN	Completed	Owner maintenance	Completed	Completed	Completed	Completed	Completed	